

FOOT OF FOOT




Fig. 1

09901310-100501




Fig. 2




FIG. 3A




FIG. 3B

FIG. 4




FIG. 4






Fig. 5

FO500F" OF EF0660



6A


SEM Micrograph of Group B at 300x after Electrochemical Test.




6B

SEM Micrograph of Group B at 700x after electrochemical test.

0901310 10501
T0500T 07E70660




7A




7B

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test indicates intergranular corrosion attacks.

09901310-100501




7C




7D

SEM micrographs of the Hayes CrCoMo sample after ASTM F746 corrosion test exhibiting corrosion attacks.

105001-01E0660



8A



8B

SEM micrographs of the Hayes CrCo sample prior to any corrosion test.